

Train #		Car #									Process Stage		Inspector		Date	Page	
215		TC1		X	M1	M2	M3	M4	TC2	FR2010 PC02	Amo Naledi/Eddie		28/02/2021				
Item	Defect Code	Demerit Class	Description of Defects	Localisation <small>(Interior, underframe, roof etc)</small>	End <small>(1) or (2)</small>	Side <small>Left (L) or Right (R)</small>	Action Required <small>(Ready to fix/Part needed/ NCR/ Work Instruction required for special process rework)</small>	Quality Sign-off	Prasa Sign-off								
1	C		Spatters on EUF2 (CB2210)	EUF2	2	L/R											
2	C		Spatters on UF bracket (leveling) CB1230		2	L											

GIBELQ

GIB0000000380

Rev A0

Defects Report

29/03/2017
4/5 Pages

Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Date	Page
215	M4					X		PC02	Selby Naledi + Amo	01/03/2024	1 of 1
Item	Defect Code	Demerit Class	Description of Defects	Localisation <small>(Interior, underframe, roof etc)</small>	End <small>(1) or (2)</small>	Side <small>Left (L) or Right (R)</small>	Action Required <small>(Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)</small>	Quality Sign-off	Prasa Sign-off		
1		C	General paint touch-ups on the Euf	EUF	1+2	L+R					
2		C	Detaching sealant on panel	EUF1	1	L					
3		C	Burn through on sidewall End 1 LHS lower module	Sidewall	1	L					

[illegible]

Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Date	Page	OF
215	TC2							PC02 PRASA	LEONARD Richmond			
Item	Defect Code	Demerit Class	Description of Defects	Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work Instruction required for special process rework)	Quality Sign-off	Prasa Sign-off			
1			Head affected zone on sidesill ringwelds	UF	1 & 2	L & R	CB1/50					
			Clash flats due to lifting on end underframe	UF	1 & 2	L & R						
			Detaching sealant of UF panels									
			<p>PRASA </p> <p>CIB: </p>									