


[illegible]

Train #	209	Car #	M4	TC1	M1	M2	M3	M4	TC	Process Stage	PCOZ	Inspector	Thab Moses	Date	06/02/24	Page
Item	Defect Code	Demerit Class	Description of Defects							Localisation	End	Side	Action Required	Quality Sign-off	Prasa Sign-off	
1	*	c	General paint touch up on the EUF								1+2	L+R				
2	1	c	Hole on sealant (panel) (CB1150)								2	L				
3	2	c	Burn through on the lower panel (CB1120) x 2								2	L				
4	3	c	Flasht spots on the skin (double window end 2)								2	L				
																

[illegible]

[illegible]

[illegible]

[illegible]